From:	Matt Stone
To:	Jon Creighton
Subject:	FW: AVL MSE Wall
Date:	Wednesday, December 31, 2014 2:31:00 PM
Attachments:	image9203c7.gif@9e11d550.d99c4f54 MSE Wall - Typical Repair Procedure.pdf

---

From: Rysdon, Eric [mailto:Eric.Rysdon@rsandh.com]
Sent: Wednesday, December 31, 2014 10:50 AM
To: Matt Stone
Cc: mreisman@flyavl.com; ekuehnel@thalle.com; DeVitto, Janis; ryanz@flyavl.com
Subject: AVL MSE Wall

Mr. Stone;

Per our conversation this morning attached to this email are the proposed repair information that we received from the contractor last night. I have also send you an email link to download the original MSE wall plans as the file size was too large to email.

As we discussed you will send out to us the required paperwork for the contractor to begin the permitting process on the MSE wall repairs.

During our construction meeting this morning we did discuss the wall and currently the contractors plans are to continue to work on safely removing damaged sections of the MSE wall panels so that they can identify those that need to be replace and begin the casting of these panels.

We will also begin gathering the testing information from the MSE wall construction and any reports referencing the wall for your office records as requested.

If you have any questions please contact me.

Sincerely

Eric Rysdon, PE
Charlotte Aviation Manager
1520 South Blvd, Suite 200
Charlotte, NC 28203
Phone: 704-940-4731 / Fax: 704-949-2672
Eric.Rysdon@rsandh.com

Visit our website at www.rsandh.com
Connect with RS&H on Facebook Twitter LinkedIn

RS&H