From: Jonathan Wainscott <jonwainscott@gmail.com>
Sent: 1/30/2020 10:46:00 PM
To: vijaykapoor@avlcouncil.com
Cc:
Subject: Riverside Drive
Attachments: riverside google street view.JPG, riverside bcgis 2019.JPG, riverside bcgis 2010.JPG

Hi Vijay,
Glad to see that there was an underground utilities locator on Riverside Drive on Wednesday morning, and new Slippery When Wet/Icy warning signs on each side of the road this morning. I have video of the conditions of the road both days. At 2PM today there was still no speed limit posted anywhere on northbound Riverside Drive from its beginning (at the roundabout) until past Hill Street where it is posted at 45MPH. Ken Putnam should be notified that the speed zones are inconsistent and unmarked.

To illustrate how frequent the water problem is it actually can be seen on the current Google Maps map and street view.

And on the Buncombe County GIS satellite imagery from 2019.

And 2010.

It also seems that the only way for the Hillcrest Apartments to get water would be through that corner of the property as the rest of the perimeter is bound by the highway, railroad tracks, and huge natural walls of rock beneath the I-240 bridge. It makes me wonder if that mysterious

private water line that was blamed the last time this made the news is the service line to Hillcrest. Then that makes me wonder if their service is OK and the water clean.

It was a strange coincidence that I came to Council to address this issue the same night that Council was presented info on our water service. Did you know that the City issued around 166 BWA's in 2019? That's one almost every other day. That's how fragile the system is.

--

Jonathan Wainscott

18 Reynolds Road
28806

828.367.8165